

MotoComp

Motorcycle Parts & Accessories

mcomp@mweb.co.za
www.motocomp.co.za

073 750 9697

po box 59 pennington 4184
fax 086 684 1544

Pilot Rubber Passage Plugs

MotoComp Part No	Make	OEM Part No	Model	Year
NTMRP-001SF	Honda	16010-371-004	GL1000 Goldwing	75-79
NTMRP-002SF	Honda	16010-425-671	CB750 Custom	80-81
		16010-461-781	CB750 Super Sport	79-81
		16010-469-004	CB 750K	79-82
			CB750L Limited	79
			CB900C Custom	80-82
			CB1000 Custom	83
			CBX (1047cc)	79
NTMRP-002SF	Suzuki	13357-44080	GN125Z / D	82-83
			GN125EN / EP / ER/ ES	92-95
			GN400T / XT / XX	80-81
			GN400TX / TZ	81-82
			SP400T	80
			GS450ED	83
			GS450GAZ GAD	82-83
			GS450GAF	85
			GS450LTD	
			GS450LF / LG / LJ	85-88
			GS450TXD	83
			GS550ET	80
			GS550LT / LX / LZ	80-82
			GS550MZ Katana	82
			GS550TX	81
			GS650EX / EZ	81-82
			GS650GX / GZ / GD	81-83
			GS650GLX / GLZ / GLD	81-83
			GS650MD Katana	83
			GS750EF / ESF	85
			GS750ET / EX / EZ	80-82
			GS750ED / ESD	83
			GS750LTD / LX	80-81
			GS750SD Katana	83
			GS750TZ / TD	82-83
			GS850GT / GX / GZ / GD	80-83
			GS850GLT / GLX / GLZ / GLD	80-83
			GS1000GT / GX	80-81
			GS1000ET / ST	80
			GS1000SZ Katana	82
			GS1100ET / EX / EZ / ED / ESD	80-83
			GS1000GZ / GLZ / GD / GLD	82-83
			GS1100KZ-GKE	82-84
			GS1100LT	80
			GS1100 Katana	83
			GS1150ES3 - EF2	83-85
			GS1150EG / ESG	86
NTMRP-002SF	Yamaha	3F7-14991-00	XS650G / H Special II	80-81
			XS650G / SH Special II	80-81
			XS650SJ / SK Heritage Special	82-83
			XS1100G / H	80-81
			XS1100G / LH	80-81
			XS1100SC / SH	80-81
NTMRP-001S	Honda		GL1000 Goldwing	

Note

NTMRP-001S uses FPM type material that does not swell -and could block fuel feed to the idle jet

If using the 18-4688 in a GL1000 carb is wise to cut the under shoulder length down by approx 0.3mm